

Nick “

Attached please find the dust monitoring conducted on Friday June 29, 2007. The dust monitor on-site was a hand held device used by the field engineer in the area of the stadium demolition. The monitoring results are within an acceptable range. In addition, visible dust was not observed at the fence line of the subject site.

If you have any questions, please call.

Peter J. DeChaves