

Nick “

Attached please find the dust monitoring results for monitoring conducted today (7/2/07) during demolition activities. The dust monitors were located at the fence line along Hull Street at each end of the stadium. The monitoring results are within an acceptable range. In addition, visible dust was not observed at the fence line of the subject site.

If you have any questions, please call.

Peter J. DeChaves